Work Order ID 53404

D

November 03, 2009 3:46:45 PM



Page 1

Item ID:

D2989-041

Accept

Setup Start

Stop



Revision ID:

Item Name: Basket Lid Assembly

11/4/2009 Start Qty: 1.00

Req'd Qty: 1.00



Date:

Cust Item ID:

Customer:

Reference:

Start Date:

Approvals:

Required Date: 11/11/2009

Process Plan:

Date: Tooling:

SPC (Y/N):

Date:

Date:

Start

Stop



QC:

Sequence ID/ Work Center ID Operation Description

Set Up/ **Run Hours** Draw Number

Draw Plan Rev. Code

Reject Accept **Qty Qty**

Run

Reject

Insp. Number Stamp

Draw Nbr Revision Nbr D2989 Rev D

100

Large Fab

Large Fab

Memo

0.00

0.00

匠

Large Fab

1- assemble all ribs and both D2581 in DT9445 jig, weld as per dwg D2989 V D51 9473

2- tack weld mesh on basket as per dwg D2989 using DT9445 jig

****cut cutouts with zip cut as per dwg D3832****

3- remove from jig and weld lable plate as per dwg D2989 A/R ER316 S.S. Rod Batch: MIG9213

110

QC9- Inspect visual per QSI004- Fusion Welds

0.00



Quality Control

Memo

0.00

09.11.10

Cp 09 11 See Ent C

W/O:			WC	ORK ORDER CHAN	GES					
DATE	STEP	PRO	CEDURE CHA	NGE	·	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-				
									!	
	<u></u>			100						
Part No	:	PAR #:	Fault Cate	gory:	NCF	R: Yes I	No DQ	\ :	Date:	
	Resolution:			n:	QA:	N/C CId	sed:		Date:	
NCR:		\	WORK ORD	ER NON-CONFORM	IANCE	(NCR)			
DATE STEP		Description of NC			ection B	Ciam 0	Verific	ation		Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
							}			
					,					
	}									

Work Order ID 53404

D

November 03, 2009 3:46:46 PM



Page 2

Item ID:

D2989-041

Accept

Setup Start

Stop



Revision ID:

Start Date:

Item Name: Basket Lid Assembly

Required Date: 11/11/2009

11/4/2009

Start Otv: 1.00

Rea'd Oty: 1.00



Date: _____

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: Date:

Tooling: SPC (Y/N): Date:

Date:

Run Start



Sequence ID/ Work Center ID

120

OC

Ouality Control

Operation Description

OC5- Inspect part completeness to step on W/O

Memo

Memo

Set Up/ Run Hours

0.00

0.00

Draw Number Draw Rev.

Plan Accept Qty Code

Reject Reject **Qty** Number

Stop

Insp. Stamp



Powder Coating

White Gloss(Ref:4.3.5.2) per OSI005 4.3-Steel

0.00

=> LN 09(1/1/

1- Plug holes prior to powder coating

M11214B

2-Powder Coat White (Ref. 4.3.5.2) D2989-041 as per QSI 005 4.3 & Dwg D2989

1ST COAT:

7:IJAM START TIME: 4000F OVEN TEMPERATURE: FINISH TIME:

7:45 AM

2ND COAT:

START TIME:

OVEN TEMPERATURE: FINISH TIME:

10mar

Dart Aerospace Ltd	Dart	Aero	space	: Ltd
--------------------	------	------	-------	-------

	-												
W/O:			WORK ORDER CHANGES										
DATE	STEP	PR	OCEDURE CHA	OCEDURE CHANGE			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
	Yesper and the second s												
							-						
				· · · · · · · · · · · · · · · · · · ·									
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Ye	s No DQ	A :	Date: _					
	Res	solution:	Dispositio	n:	_ QA: N/C	Closed:		Date:					
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NO	R)		The de 5 Per					
DATE	STEP	Description of NC	· -		ion B	Verifi	cation	Approval	Approval				
	J.E.	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da		tion C	Chief Eng	QC Inspector				
•													
					1	l l		1	ľ				

Work Order ID 53404

November 03, 2009 3:46:46 PM

D

Required Date: 11/11/2009



Page 3

Item ID:

D2989-041

Accept

Setup Start

Stop

Stop



Revision ID: Item Name:

Start Date:

Basket Lid Assembly

11/4/2009

Start Otv: 1.00

Rea'd Otv: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Draw

Rev.

Date:

Run Start

OC:

Date:

Identify as per dwg & Stock Location: U/O \$346 \

SPC (Y/N):

Set Up/

Run Hours

Draw Number

Plan Code

BR 09-11-11 0 \$

Accept Oty

Reject Oty

Reject Insp. Number Stamp

Sequence ID/ **Work Center ID**

131

HandFinish

Hand Finishing

Operation Description

Wing Walk as per dwg QSI005 4.4 Batch 1062300

Memo

0.00

Mask lid prior to spray paint black and wing walk as per dwg A/R Spray paint black batch: 112437.

140

QC

OC3-Inspect Part Finish

Memo

0.00

0.00

9/1/11 <u>U</u>____

Quality Control

141

Packaging

Memo

0.00

Packaging

Dart Aerospace Ltd	Dart	Aero	space	Ltd
---------------------------	-------------	------	-------	-----

W/O:			WC	RK ORDER CHANG	GES	44				
DATE	STEP	PR	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
·								<u> </u>		
<u> </u>										
Part No	•	PAR #:	Fault Cate	gory:	_ NCR	: Yes	No DQ	A:	Date:	
	Re	solution:	Disposition	1:	QA:	N/C CId	sed:	····	Date: _	
NCR:			WORK ORD	R NON-CONFORM	ANCE	(NCR)			
DATE	STEP	Description of NC		tion B	0:	Verific	cation	Approval	Approval	
5,112		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
							!			
								,		
						<u> </u>				
1	1				İ				1	

Work Order ID 53404

November 03, 2009 3:46:46 PM



Page 4

Item ID:

D2989-041

Accept

Setup Start



Revision ID:

D Basket Lid Assembly Item Name:

Stop

Start Date:

11/4/2009

Start Qty: 1.00 Req'd Qty: 1.00

Operation

Description

Cust Item ID: Customer:

Reference:

Approvals:

Process Plan: Date:

Tooling:

Date:

Run Start



Required Date: 11/11/2009

Date: _____

QC21- Final Inspection - Work Order Release

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop

Sequence ID/

Work Center ID

QC

Memo

0.00

0.00

Draw Number

Draw Rev.

Plan Accept Qty Code

Reject Qty

Reject Number

Insp. Stamp

Quality Control

Da	art	Aer	os	pac	e L	td
----	-----	-----	----	-----	-----	----

	•									
W/O:			WC	ORK ORDER CHANC	GES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	ı	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					1					
			· · · · · · · · · · · · · · · · · · ·							
!										
Part No	•	PAR #:	Fault Cate	gory:	NCR: Y	es No	DQ/	A:	Date:	
		esolution:								
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	CR)				
DATE	STEP	Description of NC		· · · · · · · · · · · · · · · · · · ·	tion B		Verific	ation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		ın & ate	Secti		Chief Eng	QC Inspector
									, , , , , , , , , , , , , , , , , , , ,	
							-			
										-

November 03, 2009 3:46:45 PM

Work Order ID: 53404

Parent Item:

D2989-041RevD

Parent Item Name:

Basket Lid Assembly

Manufactured

No

Comments:



Start Date: 11/4/2009

Required Date: 11/11/2009

Start Oty: 1.00

Required Oty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2221-1RevH		Manufactured	No			100	Each	23.0000	2.0000			
				<u>Warehou</u> <u>Loca</u>		Loc	<u>Oty</u>	Loc Code				

Main Warehouse ST 48101 Main Warehouse WA 22 PD 09.11.05 51872 10 53213 12 100 Each 11.0000 1.0000

D2506RevF

Label Plate

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
ST	1		
44275	1		
Main Warehouse			
WA	10		
52834	10		10 09.11.05

Page 1

Dart	Δει	'OSI	າຂດ	ا م	td
vait	AC:	voi	Jac	CL	···

W/O:			WORK ORDER CHANGES							
DATE	STEP	PR	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	,									
l										
i										
Part No	:	PAR #:	Fault Cate	gory:	NCR	: Yes	No DQ	A:	Date:	J
		esolution:								
NCR:			WORK ORD	ER NON-CONFORM	MANCE	(NCR)			·
DATE	CTED	Description of NC			ection B	<u>,</u> ,,	Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Secti		Chief Eng	QC Inspector
,										
										:
								-		

November 03, 2009 3:46:45 PM

Page 2

Work Order ID: 53404

D2989-041RevD

Parent Item Name:

Basket Lid Assembly

Manufactured

No

Comments:

Parent Item:



Start Date: 11/4/2009

Required Date: 11/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2512-7RevE		Manufactured	No			100	Each	4.0000	1.0000			

Rib

<u>Warehouse</u>	Loc	<u>Oty</u>	Loc Code			
Location						
Main Warehouse						
ST		4				
48666		4			RD	09.11
	100	Each	56.0000	2.0000		

D2581RevA1

Mounting Bracket

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST	12	
46086	2	
48428	1	
51120	9	
Main Warehouse		
WA	44	
50872	1	

43

1.05

PD 09.11.05

51745

Dart Aerospac	e:	Ltd
---------------	----	-----

W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CH	ANGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										i
Part No	•	PAR #:	Fault Cat	egory:	_ NCR:	Yes N	lo DQ /	A:	Date: _	
		solution:								
NCR:			WORK ORE	DER NON-CONFORMA	ANCE (I	VCR)			.,,,,,,	4-3-3c.
DATE	CTED	Description of NC	Corrective Action Section			Verific	ation	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section		Chief Eng	QC Inspector
								1		

November 03, 2009 3:46:45 PM

Page 3

Work Order ID: 53404

Parent Item:

D2989-041RevD

Parent Item Name: Basket Lid Assembly

Comments:



Start Date: 11/4/2009

Required Date: 11/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2989-13RevD		Manufactured	No			100	Each	4.0000	2.0000			

Rib

Warehouse	Loc	: Oty	Loc Code		
Location					
Main Warehouse					
WA		4			
51864		4			PD 09.11.05
	100	Fach	9 0000	2 0000	

D2989-19RevD

Manufactured

2.0000

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
ST	1		
44867	1		
Main Warehouse			
WA	8		
51338	4		PD 09.11.05
51874	4		

Dart Aerospace Ltd	Da	art	Aer	osp	ace	Ltd
--------------------	----	-----	-----	-----	-----	-----

	•								
W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			10 (0.00 d)						
Part No	:	PAR #:	Fault Cat	tegory:	NCR: Yes	No DQ	A:	Date: _	
		esolution:							
NCR:			WORK ORI	DER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sect	ion C	Chief Eng	QC Inspector
		·							
						i			
								ţ	
						j			

November 03, 2009 3:46:45 PM

Page 4

Work Order ID: 53404

Parent Item:

Comments:

D2989-041RevD

Parent Item Name:

Basket Lid Assembly

Manufactured

No

Start Date: 11/4/2009

Required Date: 11/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3832-3RevA		Manufactured	No			100	Each	4.0000	1.0000		М	

Mesh (Lid)

Warehouse Location	<u>Lo</u>	<u>c Oty</u>	Loc Code			
Location						
Main Warehouse						
ST		4				
48608		1				
51865		3			PD 09.11.09	
	100	Each	15.0000	2.0000	• • • • • • • • • • • • • • • • • • • •	

D3833-3RevA

Mesh (Lid End)

Warehouse Location	Loc Oty	Loc Code	
Main Warehouse			
ST	15		
46308	3		
53136	12		

PD 09.11.09

Dart Aerosp	ace Ltd
-------------	---------

Part No: PAR #: Fault Category: NCR: Yes No DQA: Date:	W/O:		- 04 - 0.	W	ORK ORDER CHANG	SES	***		VIII.	
Part No:	DATE ST	TEP	PRO	OCEDURE CHA	ANGE	В	у	Date Qty	Chief Eng /	Approval QC Inspector
				···						
	Part No:		PAR #:	Fault Cate	egory:	NCR: `	Yes N	o DQA :	Date: _	
NCR: WORK ORDER NON-CONFORMANCE (NCR)	NCR:		V	WORK ORE	ER NON-CONFORM	ANCE (I	VCR)			
DATE STEP Description of NC Corrective Action Section B Verification Approval Approval	DATE ST	TED D	Description of NC				Verification	Approval	Approval	
MAIL OILE	DAIL 31									QC Inspector
								i		
						i				
			·							
								}		
					A-7					
		,								
									Ì	

November 03, 2009 3:46:45 PM

Work Order ID: 53404

Parent Item:

D2989-041RevD

Parent Item Name: Basket Lid Assembly

Comments:



No

Start Date: 11/4/2009

Required Date: 11/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3836-041RevA		Manufactured	No			100	Each	4.0000	1.0000			

Rib Assembly (Basket Lid, LH)

Warehouse	Loc	<u>Oty</u>	Loc Code		
Location					
Main Warehouse					
ST		2			
51336		2			PD 09.11.05
Main Warehouse					
WA		2			WHAT A STATE OF THE STATE OF TH
53129		2			
	100	Each	4.0000	1.0000	

Manufactured

Rib Assembly (Basket Lid, RH)

D3836-042RevA

Warehouse Location	Loc Qty	Loc Code	
Main Warehouse			
ST	2		
51337	2		
Main Warehouse			
WA	2		
53130	2		

5346 53436 PD 09.11.05

Dart Aerospace Ltd

W/O:	•		W	ORK ORDER CHANG	ES				·····	
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	(Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			-				******			
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Ye	es No	DQ	A:	Date: _	
		esolution:								
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (N	CR)				
DATE	STEP	Description of NC Corrective Action			ion B		Verific	cation	Approval	Approval
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Section C		Chief Eng	QC Inspector
<u> </u>										
V-1_ #***										
]				

November 03, 2009 3:46:45 PM

Page 6

Work Order ID: 53404

D2989-041RevD

Parent Item Name: Basket Lid Assembly

Comments:

Parent Item:



Start Date: 11/4/2009

Required Date: 11/11/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3852-041RevA		Manufactured	No			100	Each	4.0000	1.0000			

Rib Assembly

Warehouse	Loc	Oty	Loc Code		
Location					
Main Warehouse					
ST		4			
51333		2			PD
53127		2			
,	100	Each	4.0000	1.0000	

09.11.05

D3852-042RevA

Manufactured No




Rib Assembly

Warehouse Location	Loc Oty	Loc Code	
Main Warehouse			
ST	4		
51332	2		
53126	2		

PD 09.11.05


Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PR	OCEDURE CHA	INGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			e <u></u>							
Part No	:	PAR #:	Fault Cate	egory:	_ NCF	: Yes	No DQ	4 :	_ Date: _	
	Re	esolution:	Disposition	on:	QA:	N/C Clo	sed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR))			
DATE	STEP	Description of NC Corrective Action						erification Appro	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
										:
				in the control of the						
							į			




Dart /	Aeros	pace	Ltd
--------	-------	------	-----

W/O:			W	ORK ORDER CHANG	SES						
DATE	STEP	PRO	OCEDURE CHA			By Date Qty Ch			Approval Chief Eng / Prod Mgr	ng / Approvar	
				Maria de la companya del companya de la companya de la companya del companya de la companya de l					l		
Part No	:	PAR #:	Fault Cate	egory:	_ NCF	R: Yes	No DQ	4 :	Date:		
	R	esolution:	Disposition	on:	QA:	N/C CId	sed:		Date: _		
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	CTED	Description of NC	Description of NC Corrective Action			Section B Verif			Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector	
1											




Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANGI	ES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	By Date Qty Chic			Approval Agar Approval QC Inspector	
								1 100 mg.		
				·				•		
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes I	No DQ	A:	_ Date: _		
		olution:								
NCR:				ER NON-CONFORMA						
DATE	0750	Description of NC	cription of NC Corrective Action			Verific	/erification Ap		Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Approval Chief Eng	QC Inspector	
						j				




Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	ES							
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	By Date Qty Chief Er			Approval Chief Eng / Prod Mgr	Approvar		
									. , , ,			
Part No:		PAR #:	Fault Cate	egory:	_ NCR: Y	es N	lo DQ	A:	_ Date: _	<u> </u>		
	R	esolution:	Disposition	on:	_ QA: N/	A: N/C Closed: Date:						
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (N	ICR)						
DATE	STEP	Description of NC			ion B		Verific	cation	ion Approval Approv	Approval		
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		gn & late		ion C		QC Inspector		
										,		
1					1					ŀ		



Dart A	erospace	Ltd
--------	----------	------------

W/O:			W	ORK ORDER CHANG	SES						
DATE STEP		PRO	OCEDURE CHA	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No:		PAR #:	Fault Cate	egory:	_ NCR	: Yes I	No DQA	\ :	_ Date: _		
Resolution:			Disposition	on:	QA:	N/C CId	Closed: Date:				
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC			tion B	0: 0	- Verific	ation	Approval	Approval	
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector	
					į						
		,									
					:						
							1		[j	



Dart Aerosp	ace Ltd	
--------------------	---------	--

	<u> </u>										
W/O:			W	ORK ORDER CHANG	ES						
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
,						···					
								<u> </u>			
Part No:		PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A:	_ Date:			
	R	esolution:	Disposiți	on:	QA: N/C Closed: Date:						
NCR:		\	WORK ORI	DER NON-CONFORMA	ANCE (NCF	R)	·				
DATE	STEP	Description of NC		·	ion B	Verific	cation	Y Chief Eng / QC In Prod Mgr Date: Date: Approval Approval	Approval		
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	on C		QC Inspector		
							:				
	·										
								!			